

## TECHNICAL INFORMATION

**Document:** TI\_T318\_20

**Date:** 09/10/2019

**Subject:** ESA AV Mounts

Reference:	Table	Item	Code
	22	14	ORN4036

**Accomplishment:** immediate

The shifter actuator (ESA) is installed on AV mounts. The AV installation is realized with specific rubber rings, please refer to the elements with #1 in the picture below.




Figure 1

The rubber ring (p/n ORN4036) should be inspected each 1000 km and must be replaced before 3000 km.