

TECHNICAL BULLETIN

Document: TB_T318_014_FRregional
Date: 07/08/2019
Subject: LH threaded Hub and Wheel Nut

Reference:	Table	Item	Code
	12B	3	24 12 008
	12A	10	24 12 025
	16C	3	24 16 008
	16A	1	24 12 025
	12A	5	24 12 028
	16B	1	24 12 028

Accomplishment: 29/08/2019

Tatuus will supply a replacement for the Right-Hand Threaded Hubs and Wheel Nuts installed on the RIGHT side of the T318 chassis.

The new hub installed on the right side of the car (Front: 24 12 004 / Rear: 24 16 004).

The new Wheel Left Threaded Nut (24 12 28) will replace the existing one (24 12 027) installed on the right corners.

Installation	Description	Q.ty	OLD SPEC (to be returned)	NEW SPEC (supplied by Tatuus)
Front RIGHT corner	Front Hub	1	24 12 008	24 12 052
Rear RIGHT corner	Rear Hub	1	24 16 008	24 16 052
Right side of the car	Wheel Nut	2	24 12 027	24 12 028
All corners	Wheel Retaining plug	4	24 12 025	24 12 025 (updated)

Teams are invited to return two old spec hub and wheel nuts for each car together with the four Wheel Retaining plug (24 12 025).

Tatuus is available to service the complete upright in its workshop on the following dates:

Formula Regional Europe: August 26, 27, 28.

Teams are invited to contact Tatuus in order to reserve a slot.