

## **TECHNICAL BULLETIN**

**Document:** TB\_T318\_025

**Date:** 20/12/2019

**Subject:** ESA Maintenance

Reference: Table Item Code

22 07 083803441800 (old spec) 083803517800 (new spec)

· ·

**Accomplishment:** 31 January 2020

Following the inspection of ESA actuators with significant working life, it has been identified a lifespan limit of  $10'000 \, \mathrm{km}$ .

Teams are required to return the actuators by January  $31^{st}$  2020 in order to service them. Two options are proposed:

Minimum service on the critical components: 1425,00€
Full service including motor replacement: 2043,00€

The proposed tariffs will only be available before January  $31^{\rm st}$  2020. After this date the pricing will be quoted as single service.

The updated actuators will be identified with the new part number 083803517800.